
Corridor 5: Old Baltimore Pike



Progress in Traffic Responsive Signalization (TRS) Implementation

273

	Implementation	Progress
	Timing Improvements Implemented	
	Traffic Monitoring Equipment Installed	
	Signals Brought Online with TMC	
_	Signal Software Upgrades	
	Converted to Traffic Responsive System (TRS)	

Capital Projects Along Corridor

7	Capital Frojects Along Corridor								
C	INTERSECTION	STATUS							
	Old Baltimore Pk. & Salem Church Rd. (West)	Identified in the Highways Safety Improvement Program (HSIP). Scheduled for construction in FY 2017 (\$1,000,000).							
	SR 72 & Old Baltimore Pk.	Identified in the Highways Safety Improvement Program (HSIP). Scheduled for construction in FY 2017 (\$800,000).							
X	SR-896 & Old Baltimore Pk.	No planned/programmed improvements.							

Possible Improvement Options for Priority Intersections

INTERSECTION	EXISTING VOLUME LOS		DEMAND OVERAGE		IMPROVED VOLUME LOS		OPTIONS
INTERSECTION	AM	PM	AM	PM	AM	PM	OPTIONS
Old Baltimore Pk. & Salem Church Rd. (West)	(A)	=0 <u>=</u>	1	149	A*	С	1. Provide a 2nd WB left turn lane on OBP.
SR-896 & Old	F F	₩ , ,	406	403	D	D	Provide 3 thru lanes in NB & SB direction and 1 thru lane in the WB direction (currently L/LT)
Baltimore Pk.		₹ 1111			F	Е	2. Analyzed as 8 - phase operation.
	,	,			Е	F	3. Change lane assignment to triple left turn for Old Baltimore Pk. EB.

Mean Travel Times

East Bound

AM: 12.6 min PM: 9.8 min

West Bound

AM: 13.2 min PM: 12.6 min

