


Existing Conditions - Pedestrian & Bicycle

Comments

- Pedestrian and bicycle facilities are limited along the SR 141 Corridor throughout the Study Area
- Brandywine Creek presents a barrier to pedestrian and bike connectivity
- Bikeable shoulders along SR 141 offer opportunities for improved amenities such as cycle tracks, shared use paths or bike lanes with separate pedestrian facilities
- Extensive opportunities for pedestrian and bike connectivity exist throughout the study area to access neighborhoods, businesses, and recreational destinations



WILMAPCO

