

Appendix B Mapping of existing conditions

- Transit and Pedestrian Counts
- Land Use
- Intersection Level of Service
- Population
- Accident Locations

Transit Routes, Transit Stops & Pedestrian Counts




Land Use



Intersection Level of Service



2000 Census Blocks



Accident Locations








Shipley Street Improvements- Existing Conditions

MARKAGO ENTE



Shipley Street Improvements- Existing Conditions

WILMAPGO HINTE

